REDUCING COIL BREAK REJECTION AT HOT SKIN PASS MILL PT KRAKATAU STEEL

Dicky Mardiana and Mursyid Hasan Basri School of Business and Management Institut Teknologi Bandung, Indonesia dicky.mardiana@krakatausteel.com

Abstract—Coil break rejection at Hot Skin Pass Mill PT Krakatau Steel is a repetitive claim from consumer and target of quality objective is still out of target. Coil break is surface defect of hot rolled coil with appearance of surface looks some areas of small lines transverse to rolling direction, low contrast to surface white or black lines. Lower yielding point of the hot rolled coil tends to have coil break rejection. Hot Skin Pass Mill (HSPM) is dedicated to prevent coil break. Anti Coil Break is the equipment at the entry section of HSPM which has main function to prevent coil break. If this equipment works properly then coil break rejection on the surface of strip can be prevented. Engineering, operation, and organization category can influence the rejection. Engineering: Anti Coil Break parameter, inspection of equipment, and quality of strip inspection. Operation: Adjustment of Finishing Temperature-Coiling Temperature and operation parameter HSPM. Organization: Span of control too wide and organization alignment. Each factor will be analyzed by Root cause analysis find the root of problem. Each category of engineering, operation, and organization will be analyzed to recommend as implementation plan. Alternative solutions proposed are: improvement of equipment reliability, redesign Anti Coil Break Roll, implementation of Statistical Process Control, review Quality Product Level, empowerment of structures, and alignment of organization. Each alternative was evaluated to propose as implementation plan. Implementation plan consists of the mandatory plan or the highest priority of each category.

Keywords : coil break, PT Krakatau Steel, hot rolled coil, yielding point, finishing temperature, coiling temperature.

1. Introduction

PT Krakatau Steel (PTKS) is the first and the biggest integrated steel at Indonesia. Steel quality is the main concern of PTKS and the quality is better than the competitor at Indonesia. At the end of 2011, PT Krakatau Steel got coil break claims from consumer. Coil break is surface defect. The appearance of surface looks some areas of small lines transverse to rolling direction. This appearance often with low contrast to surface white or black lines, as indicated at Figure 1.




Figure 1. General Appearance of Coil Break

1.1 Repetitive Claim

Looking back at the history of HSPM, it was very interesting that this claim was already happened on 2008. This claim came from the same consumer, Papajaya, Hamasa, and Lion Metal Works.




Figure 2. Coil Break Claim 2008 and 2011

Some corrective actions done in 2008 and rejection was reduced significantly then the claim was disappeared. In 2011 this claim came again from the same consumer. Although HSPM always can overcome the coil break rejection problem but repetitive claim is still potential problem.

1.2 Quality Objective

Online coil break rejection always happen even in the normal condition. This online coil break rejection sometimes is out of target.





Figure 3. Normal Online Coil Break Rejection at HSPM 2008 and 2012

The level of target is 1% per month, it is around 500 MT per month. Normal online rejection means rejection without claim condition. The normal online rejection in period 2008 and 2012 can be seen at Figure 3.

2. Business Exploration

2.1 Conceptual Framework

Conceptual frame work is the first step to identify coil break claim or rejection and to define what defect actually happen, and at the end will give basic frame work to solve the issue. Figure 4. is the conceptual framework to analyse what factors can influence the coil break rejection.



Paul, Ahmed, and Megaheed, 2010, stated that operational factor such as rolling parameter at HSM can influence coil break rejection at HSPM. Watanabe, 2005, stated that engineering and operational factor at HSPM, will strong influence to coil break rejection. Some equipment related to surface of strip at HSPM was suspected not in the standard condition. It might be some miss alignment, over clearance, mechanical looseness, or some parts exceeded the life time. Leakage at hydraulic system can influence also the pressure, the pressure will be fluctuation.

2.1.1 Yielding and Cooling Rate

Refer to the *Megahed*, *Hsun H*, *and Sober*, coil breaks is the surface defect which is the result of local yielding phenomena and uncoiling problem. This local yielding will cause crease or ridge on the surface of the strip forming irregular interval and parallel. This crease, ridge, or line marks is perpendicular to the rolling direction.




Figure 5. Yield Point Elongation and Coil Break

This yielding phenomena is caused by inhomeginity of microstructure. Then this inhomogenity of microstructure is affected by reduction, cooling rate, and chemical element contained in the steel, as indicated at Figure 5.

2.1.2 Parameter of HSPM

Coil breaks occur transverse to the rolling direction when uncoiling and appear at irregular interval. It results from the presence of a yield-point elongation attributtable yo insufficient hot skin pass rolling and uncoiling parameter. All of Hot Skin Pass Mill in the world always installs Anti Coil Break Roll or Pressure Roll to eliminate coil breaks defect, such as Blue Scope Steel, Essar, and also Hot Skin Pass Mill at Krakatau Steel. Some HSPM parameters besides anti coil breaks practices have to be considered to eliminate coil breaks defect. These parameters are entry tension, exit tension, pressure of anti coil break roll, speed process, and roll force.

2.1.3 Problem Identification

A. Rating of Coil Break

After evaluating the case of online rejection due to coil break period November-December 2011, acquired defect rating. Rating 1 and 2 are acceptable, while rating 3 and 4 can not be accepted by consumers. Here is the rating classification at Table 1:

Rating 1 Rating 2 > No break line marks > Small break line Accepted by Consumer marks Accepted by Consumer Rating 3 Rating 4 Break line marks > Heavy break line Not accepted by marks Consumer Not accepted by Consumer

Table 1. Rating Classification of Coil Break Rejection

B. Product Specification Rejected

Upon closer investigation found that not all of the products processed at HSPM would have coil breaks defect. Only products by grade SPHC, BJPC, and SPHT1 have suffered coil breaks. Here are the product specifications of coil break rejected, as seen at Table 2.

No. Description **SPHC** SPHT1 **BJPC** 1 Equivalent JIS G JIS G SNI07-0601-Material 3131 3132 2006 Internal OA0603 OA0603 2 OA0603 Grade OA0804 OA0804 OA0804 3 Tensile 270 270 270 Strength (min) (min) (min) (N/mm²)

Table 2. Product Specification of Coil Break Rejected

This was the dominant product of HSPM as seen at Table 3.

Table 3. Production Volume at HSPM (2009-2012)

Product	2009	2010	2011	2012
Specification	(MT)	(MT)	(MT)	(MT)
SPHC	182.556	190.214	176.943	184.881
BJPC	126.860	132.999	169.047	177.519
SPHT1	47.078	62.568	73.454	78.183
Others	133.887	97.850	89.387	77.872
Total	490.381	483.631	508.831	518.456

The application of this product is for commercial quality, such as pipe and tube, construction, office and home appliance.

2.2 Analysis of Business Situation

2.2.1 Existing Operation Parameter

Here are the relevant parameter processes at HSM to produce SPHC, SPHT1, and BJPC in relation to coil break rejection analysis as described at Table 4:

Item Uni Parameter t Product SPHC, BJPC, and Specification SPHT1 °C Reheating 1220 - 1250 Furnace oC Finishing Temp. 840 ± 15 ((FT) OC. Coiling Temp. 560 ± 10 (CT) **Last Active Stand** reduction at % 10 (min) Finishing Mill

Table 4. Operation Parameter Standard of HSM

This parameter was already established since April 2008, when the coil break rejection happened at that time. *Refer to Paul, Ahmed, and Hsun Hu*, items to be analyzed at HSM relating to coil break rejection is Finishing Temperature and Coiling Temperature. Trial at 2008 explained us that FT 840 \pm 15 $^{\circ}$ C and CT 560 \pm 10 $^{\circ}$ C is appropriate to prevent coil break rejection at HSPM.

At the same time the actual operation parameter standard at HSPM is described at Table 5. This parameter was already established since HSPM operate for the first time in 1996.

	Uni	Thickne	Thickness (mm)		
Item	Uni	1.80 -	3.55 -		
		3.50			
Tension at Pay Off Reel	Kg	5.000	10.00		
(max)			0		
Tension at Tension	Kg	8.000	16.00		
Reel (max)			0		
Speed (max)	mp	400	200		
Rolling Force (max)	KN	13.000			
Bending Force (max)	KN	1.300			
Pressure of Anti Coil	bar	100 - 120			
Break Roll					
Different WR diam. top	μm	2(20		
bottom		20	00		

Table 5. Operation Parameter Standard of HSPM

Anti Coil Break Roll installed at the entry section, just after Uncoiler, is the equipment dedicated to anticipate coil break rejection. This equipment must operate well at any time so the condition must be perfect to reach the pressure determined.

2.2.2 Existing Quality Regulation

It is not all HSM product will be sent to HSPM, only around 30% of that being processed at HSPM. Material Product Development (MPD) Department has been already recommended which product must be processed at HSPM according to consumer requirement and product specification, as described at Table 6. This quality regulation is dedicated to improve flatness problem and prevent coil break rejection. This quality rejection has already implemented since 1999, 3 years after HSPM operated at the middle of 1996.

Prod	Dimensio	n (mm)	Cros Codo
uct	Thickness	Width	Spec. Code
	t ≤ 2.10	All	All
	2.11≤ t ≤	W ≤	SPHC (series), BJPC,
	3.99	1550	SPHT
	2 11/+/		SAE1006PO,
HRC	$\begin{array}{c ccccc} \text{IRC} & 2.11 \le t \le & W \le \\ \hline 7.00 & 1550 \end{array}$	vv ≤ 1550	SAE1008PO,
	7.00	1550	SAE1010PO
		W <	HSAPH440,
	t ≤ 6.00	vv ≤ 1550	HSAPH540,
		1550	HSAPH620
HRP	t ≤ 2.10	All	All HRPO Spec.
O	2.11≤ t ≤	W ≤	All spec. code at No.
	6.00	1250	2, 3, and 4

Table 6. Regulation of HSPM Product

All HRPO products must be processed at HSPM because this product is very sensitive to flatness problem and coil break rejection. It is around 73-85% of HSPM is SPHC series, BJPC, and SPHT, as seen at Table 3.

2.2.2 Implementation of Standard Operating Procedure

In general the implementation of Standard Operating Procedure at HSM was almost be followed by operator, because all parameter was controlled automatically by system, by machine. It was only in some little cases operator can make intervention into the system, but after this intervention, maintenance staff will be fixed this problem and the system will be back into automatic mode. At HSPM too many standard can be interrupted by operator, because this HSPM not fully controlled

At HSPM too many standard can be interrupted by operator, because this HSPM not fully controlled automatically by machine. Some of operation standard was not implemented at HSPM in December 2011, as indicated at Table 7.

		Thickne	A ctu	
Item	Unit	1.80-	3.55 –	Actu al
		3.50	7.00	aı
Tension at Pay	Kg	5.000	10.000	Ok
Off Reel (max)				
Tension at	Kg	8.000	16.000	Ok
Tension Reel				
(max)				
Speed (max)	mp	400	200	Not
	m			Ok
Rolling Force	KN	13.000		Ok
(max)				
Bending Force	KN	1.3	300	Ok
(max)				

Table 7. Actual Operation Parameter of HSPM in December 2011

Pressure of Anti Coil Break Roll	bar	100 - 120	100 - 120	Not Ok
Different WR diam. top bottom	μm	200		Not Ok

The worst condition at that time the maximum speed was only 40 mpm, it means only 10% of maximum speed design. Pressure of anti coil break roll was fluctuation, sometimes pressure drop to 60 bar. It should be hydraulic problem happen at this system. This pressure fluctuation cause using of anti coil break was not optimum. Basically this stable pressure controls the elongation upon the strip being processed. Different work roll diameter top bottom not consistent, sometimes different diameter was more than 200 μ m, even can get close to 1.000 μ m at the worst condition. All this parameter can generate the coil break rejection at HSPM.

2.2.3 Corrective Action Done to Overcome Coil Break Rejection

A. Period 2008

When coil break claim happened in 2008, all of corrective actions done was at HSM due to yielding phenomena. As literature noted, that yielding phenomena can generate the coil break rejection at HRC. It would be more sensitive to coil break rejection. Yielding phenomena can control by adjusted FT, CT and reduction. All parameter, as noted at Table 8, could be achieved by HSM. There is no fixing equipment problem at HSPM but some operation standard did not implement consistently as seen at pressure of anti coil break and different work roll diameter. Task force team then gave socialization in order to implement the HSPM operation standard consistently, especially in implementation different work roll diameter and utilization of anti coil break roll.

Item Unit Parameter Actual OC Reheating Furnace 1200 -1220 Ok OC. Finishing Temp. ((FT) 840 ± 15 Ok 0C Coiling Temp. (CT) 560 ± 10 Ok Last Active Stand reduction Ok % 10 (min) at Finishing Mill

Table 8. Parameter of HSM in 2008

B. Period 2012

Looking at Table 10, at HSPM the main issues is engineering problem. Hydraulic pressure not stable, pneumatic system problem, vibration too high at roll drive, over clearance, roll not standard, and unrecorded tension. That engineering problem coming from entry section to exit section, it means almaost each section of HSPM get problem. It can be concluded that this HSPM is poor maintenance, and preventive maintenance done not dicipline. If daily or shiftly inspection doing properly and reported to planning and preventive maintenance departments, than this department can organize properly the preventive maintenance. Mechanic and operation loose control on HSPM area, because almost engineering problems are coming from mechanic and operation. Only 1 item is electric problem, that is unrecorded tension.

Internal leakage, over clearance, different diameter too high, not alignment, dirty oil and hydraulic system are engineering and operation problem at HSPM. These problems shows that HSPM is not proper maintenance and inspection. Based on literature, yielding phenomena can be approached by cooling rate. Lowering FT and CT at that temperature can reduce yielding problem but it will cause operational problem at HSM. Because FT 820 °C is too low so it can affect to vibration at the stand of finishing mil.

Table 10. Corrective Action Done at HSPM in January 2012

What	Where	Why	Wh	How
			0	
	Pressure	Internal	ME	Replace cyl.
	Roll	Leakage		& seal
	(Anti			Replace servo and filter
Hydra	Coil	Bad	ME	
ulic	Break)	Valve	IVIE	Repair and replace valve
Pressu	Auxilliar	Accumul	ME	Increase
re not	y tank	ator	ME	pressure
stable	y carric	Dirty		Flushing the
		2 ,		pipe and
				replace the
				oil
Pneum	Pinch	Wear	ME	Replace
atic	Roll 3	Cylinder		cylinder
system				pneumatic
proble	Separat	Mixed by	ME	Fixed the
m	or	oil		leakage and
				cleaning the
				separator
	Bearing	Not	ME	Replace
	Cross	standard		bearing cross
	Joint	_		joint
Vibrati	Wobler	Over	ME	Replace liner
on too	Plate	clearance	2.45	
high at	Gear	Back lash	ME	Check back
Roll Drive	Box Spindle	Not	ME	lash Check,
Dilve	Spiriule	Allign	IVIE	corrective,
		Alligii		and
				allignment
	Mill	Over	MF	Fix the wear
	Stand	Clearanc		plate
		е		
	Entry	Over	ME	Add the shim
Over	Coil Car	Clearanc		plate
Over Cleara		е		
nce	Pay Off	Over	ME	Add the shim
1100	Reel	Clearanc		plate
		е		
	Chock	Over	OP	Add the wear
	WR	Clearanc		plate
	144 .	e		
D "	Work	Over	OP	Diameter top
Roll	Roll	Diameter		n bottom
not	Λ rc ± :	De 4	0.0	almost similar
standa	Anti	Bad	OP	Replace anti
rd	Crimpin	surface		crimping roll
	g Roll			

	Pressure	Profile	OP	Replace the
	Roll	Out		roll
Unrec	Loss	Server	EL	Install New
orded	Comm"t	fault		Server
Tensio	ion			
n				

Note: ME: Mechanic, OP: Operation, EL: Electric

2.3 Root Cause Analysis




Figure 7. Root Cause Analysis of Coil Break Rejection

The yellow circles at Figure 7. are the root of problem.

Table 12. Classifying the Root

Root of	Evidence	Class
Problem		
Equipment	Over Clearance,	
not standard	Leakage,	
	Looseness	Enginoori
Poor	Too much	Engineeri
Inspection	deviation	ng
ACB not	Reliability is not	
optimum	good	
Over	HSPM overload	
Regulation		Operatio
Adjustment	Yielding points	n
FT & CT	too Low	
Low	Parameter	
Awareness	deviation	
Ignoring SOP	Low discipline	Man
Need Training	Know how	Power
and	problem	
accustomed		
Control span	Loss control from	
too wide	leader	Organizat
Organization	Agency problem	ion
not align		

Note: Man power and organizational is indirect factor.

After classifying the root of problem in RCA, found that 4 classes of issue: engineering, operational, and indirect factor. Indirect factor consist of man power and organizational. It will take a long time to

solve man power problem, because it will be too much department get involved in man power problem. It is not only production directorate but also human capital directorate. All of roots are listed then evaluate each subject listed refer to main class available, as seen at Table 12.

3. Business Solution

a. ALTERNATIVE SOLUTION OF ENGINEERING AT HSPM

3.1.1 Improvement of Equipment Reliability

Equipment reliability must be improved to guarantee all the equipment running as per manual operation. If the range pressure of anti coil break roll is 100-120 bar then the equipment cannot achieve this range of pressure, do not operate the HSPM and fix the equipment first. If tolerance was given for 99 bar then some day will be given the tolerance of 98 bar, because the reason is no significant effect.

Inspection done by HSPM maintenance staff was included: cleanliness, looseness, greasing, lubricating, clearance, wear, vibration, diameter, and over life time. Improvement of Inspection can be seen at Table 13.

Table 13. Correction of Inspection Schedule at HSPM

F		Fre	eq.	Tool
Equipment	Inspection	Now	Next	Tool
ACB Roll	Check	daily	shiftly	PG
	pressure			
Auxiliary	Check	daily	shiftly	PG
Tank	pressure			
Pinch Roll	Check	daily	shiftly	PG
	pressure			
Separator	Check	daily	shiftly	V
	leakage			
Bearing	Check	6	month	HM
Cross Joint	current	month	ly	- 1
		S		
Wobbler	Check	6	month	C
Plate	vibration	month	ly	
		S		
Gear box	Check back	6	3	DI
	lash	month	month	
		S	s 3	
Spindle	Check	6	3	T
	alignment	month	month	
		S	S	
Mill Stand	Check	yearly	6	CS
	vibration		motnh	
			S	
Entry Coil	Check	3	month	HM
Car	current	month	ly	1
		S		
Pay Off	Check	3	month	НМ
Reel	current	month	ly	- 1
		S		
Chock WR	Check	3	month	НМ
	Force	month	ly	1
		S		

Work Roll	Check	daily	shiftly	OM
	Diameter			
Anti	Check	month	weekl	V
Crimping	surface	ly	y	
Roll				

PG : Pressure Gage V : Visual HMI : Human Machine Interface

C: Caliper T: Theodolite CS: Caliper Stick OM: Outside Micrometer

Red: Proposed

The red letter indicated an improvement of inspection frequency and tool must be provided for inspection. Tool for inspection is a mandatory provided by supervisor. Inspection cannot be done perfectly without tool. This inspection standard must be implemented strictly and supervisor must check and evaluate the result of inspection daily.

3.1.2 Redesign of Anti Coil Break Roll

Figure 10 is new design of anti coil break roll recommended, consist of work roll and back up roll. This figure is designed by SIEMENS-VAI, Austria. Work roll is smaller roll directly touch the strip, and back up roll is bigger diameter and supporting the work roll.




Figure 10. New Design of Anti Coil Break Roll

Work roll of new design is smaller than roll of old design. Smaller diameter roll can press the smaller of surface area of strip then the stretch-strain become smoother. So yielding point can be improved by smaller diameter of roll, and the coil break can be prevented. New design of ACB Roll system is completely. It is not only mechanic, but also hydraulic system.

3.2 Alternative Solution of Operation

3.2.1 Implementation of Statistical Process Control

In case of adjustment parameter FT and CT, there is two different recommendation to operator : In 2008, MPD department gave recommendation FT 840 \pm 15 $^{\circ}$ C and CT was 560 \pm 10 $^{\circ}$ C, but for the same case at 2012 he gave recommendation FT 820 \pm 15 $^{\circ}$ C and CT was 520 \pm 10 $^{\circ}$ C. It was made unclear for operator. Different view between operation and quality control cause unclear parameter should be used at the HSM.

By implementing statistical process control (SPC) this issue can be evaluated more accurate. Process and operation parameter at HSM and HSPM were controlled more detail and compare to final quality.

3.2.2 Quality Product Level

Quality product level is the regulation of PTKS to match quality requirement of consumer and process route at PTKS. Quality level of each consumer is different. HRC for automotive is different level quality with HRC for commercial structure. This Quality requirement will determine the process level and process route at PTKS. By reviewing quality product level, load of HSPM can be reduced.

Looking at Table 14, this is not normal, satisfying the consumer beyond their quality requirement. More than 99% is without any requirement order of consumer. This value is too much, and PTKS must review internal quality regulation, whether it was over quality treatment.

Table 14. Annual Order and Production of HSPM 2011-2012

Year	Total	otal Total Consumer		% cons.
	Production	Order	requirement	req to
	(MT)	(MT)	(MT)	tot.order
2011	508.831	445.971	3.290	0.7%
2012	518.456	478.064	2.040	0.43%

PTKS can develop new regulation by evaluating existing regulation. Not all SPHC and BJPC for thickness $2.11 \le t \le 3.99$ and W ≤ 1550 require perfect strip flatness quality. PTKS can follow Table 15 to meet appropriate regulation. Table 15 has potential opportunity to reduce 64.000 MT of HSPM annual and can convert to 1.5 month for maintenance.

Table 15. New Quality Order Regulation Proposed of HSPM Product

Produ	Dimension (mm)		Spac Code
ct	Thickness Width		Spec. Code
	2.11≤ t ≤	W ≤	
HRC	3.00	1550	SPHC (series),
пкс	3.01≤ t ≤	W≤	BJPC
	3.99	1219	

3.3 Alternative Solution of Organizational

3.3.1 Empowerment of Structure

It is strong recommended for each position at HSPM to be closer to the HSPM. It is very important to maintain attendant time in the mill, not in the office, in order to be closer to the real condition. The standard activities of each position can be seen at Table 16.

Table 16. Standard Activities to be Done by Each Position

	Presence at HSPM per day					٥	Inspection			Basic Naintenance					Leadership			
	0-1 hr	2 hrs (min)	4 hrs (min)	8 hrs (min)	Attend daily meeting	Direct Responsible	Shiftly	Daily	Weekly	Cleaning	Lubricating	Tightening	Measuring	Oral Warning	Written Warning	Rewarding	Coaching	
Manager of HSM	0				G	G			0	0	0	0	0	0	(9	(Θ	
Manager of HSM Maintenance	0				G	G			0	0	0	0	0	(Θ	(Φ	
Chief of HSM	0				0	0			0	0	0	9	0	Θ	0	0	Θ	
Chief of HSM Maintenance	0				0	0			0	0	Θ	Θ	9	Θ	0	0	Θ	
Superintendent of HSPM		0			0	0		0		0	Θ	Θ	Θ	0	0	0	0	
Superintendent of Mechanics		0			Θ	0		0		0	0	Θ	Θ	0	0	0	0	
Superintendent of Electric		0			0	0		0		0	Θ	Θ	9	0	0	0	0	
Senior Engineer HSPM		0			0	Θ		0		0	0	0	0	0	0	0	0	
Engineer HSPM			0		0	0		0		0	0	0	0	0	0	0	Θ	
Supervisor HSPM			0		0	0		0		0	(4)	((0	0	0	0	
Supervisor Mechanics			0		0	0		0		0	0	0	0	0	0	0	0	
Supervisor Electric			0		0	0		0		0	(((9	0	0	0	0	
Foreman HSPM				0	G	0	0			0	0	0	0	0	9	0	0	
Foreman Mechanic		0	ļ.,		0	0	0			(0	0	0	Θ	Θ	0	Θ	
Foreman Electric		0			0	0	0			O	0	0	0	0	0	Θ	Θ	
Operator HSPM				0	9	0	0			0	0	0	0	0	0	0	0	
Operator Mechanics		0			0	0	0			0	0	0	0	0	0	0	0	
Operator Electric	匚	0			G	0	0			0	0	0	0	0	0	0	0	
Note:																		
0	=	Full Activity				Rew	warding means to rewad, not to be rewarded											
Ф	=	Often Activity				Coac	ning means to coach, not to be coached											
Ā	=	Rare Activity																
90	-	Less Activity																
Ŏ	=	No Ac	tivity															

It needs strong superintendent to exercise good leadership for reward, punishment, and coaching. Superintendent also practices daily inspection, attend daily meeting, and the organization needs the presence of superintendent at HSPM 2 hours daily minimum.

3.3.2 Alignment of Organization

Manager of HSM Operation, Manager of Quality Control, and Manager of Material and Product Development have to discuss the alignment of organization among them to eliminate the unclear condition during rolling SPHC at HSM. Which FT-CT for SPHC product will be implemented in rolling's program. Manager of HSM should be strong recommended as a leader of this alignment because he is the final determinant of rolling schedule and he has to save the mill and the product directly. Direct participation of senior engineer MPD, engineer MPD, and Senior Engineer of Quality Control must be improved to get accurate information.

4. Conclusion and Implementation Plan

- 1. For the short period and to control budget tightly, improvement of equipment reliability is the best solution for engineering alternatives.
 - Overhaul 2013 will be held in April 2013. This overhaul will be determinant factor to improve equipment reliability at HSPM. Corrective actions and preventive actions during overhaul must be executed appropriately.
- 2. For the long period and budget is enough, redesign ACB Roll is recommended also for engineering alternatives.
 - This project is not mandatory. If PTKS has good space budget and time, this project is strong recommended to implement. Total time will be required to implement this project is around 3 years, since budget providing up to acceptance test. For this kind of project, since contract signed up to erection is 12 months normally. Technical discussion, detail engineering discussion, erection, and test period are the key factor to succeed of redesign of ACB.
- 3. Implementation of Statistical Process Control and review quality product level are a MUST to reduce coil break rejection. Both operation alternatives are a mandatory solution and can be implemented in 2013.
- 4. Empowerment of structure has the higher priority than alignment of organization in organization alternatives.
 - The determinant stages are reposition of staff and reward-punishment. The right man on the right job and core competencies are basic requirement to select the best people to empower the structure. It will need 8 months to implement this plan.

Reference

Hsun Hu, 1983, *Effect of Solutes on Luders Strain in Low-Carbon Sheet Steels*, Metallurgical Transaction, Volume 14A, 85-91.

Kanter, R.M., 1993, Men and Women of the Corporation, 2nd edition, New York, Basic Books.

Kepner, C.H. and Tregoe, B.B., 2006, A Systematic Problem Solving and Decision Making Method, The New Rational Manager.

Paul, S.K., Ahmed, U., and Megahed, G.M., 2011, Effect of Hot Rolling Process on Microstructures and Properties of Low-Carbon Al-Killed Steels Produces Through TSCR Technology, Journal of Materials Engineering and Performance, Volume 20 (7), 1163-1170.

Richmond, O., Leslie, W.C., and Sober, R.J., 1972, *Elimination of Yield Point in Steel Sheets by Rapid Temperature Change*, Metallurgical Transaction, Volume 3, 2593-2595.

Roberts, W.L., 1987, Flat Processing of Steel, Manufacturing Engineering and Material Processing, Marcel Dekker Inc, New York.

Vladimir, G.Z., 1989, *Steel-Rolling Technology Theory and Practice*, Manufacturing Engineering and Material Processing, Marcel Dekker Inc, New York.

Watanabe, 2005, Failure Analysis Defect, 1-32.